VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3533	DATE	М	ar. 23 2015			
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation						
DESCRIPTION OF DEFECT	bolts of upper side s to be used in this noise or engine oil	On some engines for light-duty trucks, the chain stretcher and the mounting bolts of upper side skid has been tightened improperly. If the truck continues to be used in this condition, the fastening part may become loose to cause noise or engine oil leak. In the worst case, the engine will have internal damage or seize and become unable to operate.					
	COMMEDCIAL	MODEL					

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
TKG-FBA20	「FUSO CANTER」	2013~2013		8
TKG-FEA20	FUSO CANTER]	2013~2013		3
			TOTAL	11