## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3525	DATE	March 19, 2015	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to improper construction of exhaust pipe, excessive stress generated from exhaust pipe resonance at a certain engine rpm is applied on exhaust pipe, causing crack.  With exhaust pipe cracked, if continued to drive, its crack will grow and then break, and in the worst case, exhaust gas will leak and also exhaust sound will increase.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-CH41A	Burgman	2014	2697
		TOTAL	2697