

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 5 2 3	DATE	M a r . 1 7 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As manufacturing the shift lever of the transmission is inappropriate, there are some claws of which the R shape were not made as instructed. Therefore, when gear shift operation is performed, an excessive amount of load may be put on the said claw causing a crack, and if it is used continuously, the crack may be further developed and the claw may be broken. In the worst case scenario, it may become impossible to do gear shifting.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B L - R N 3 4 J	MT - 0 9	2 0 1 4	1 , 3 8 4
	MT - 0 9 A		
		TOTAL	1 , 3 8 4