

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 2 6	DATE	Mar.19.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate judgement program on the engine starting status in the engine control module (ECM) of the engine with supercharger, if the select operation of the CVT is performed quickly just after the engine start, the throttle position compensation control might be continued. Therefore the throttle opening angle can be increased, in an extreme case, the vehicle might accelerate than driver's expectation.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-E 1 2	NOTE	2 0 1 2 ~ 2 0 1 3	1 2 2, 8 5 0
		TOTAL	1 2 2, 8 5 0