

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3522	DATE	March 13,2015
MANUFACTURER	HKS CO., LTD.		
DESCRIPTION OF DEFECT	Cracking may occur on the floor panel of the vehicle which was modified to the natural gas and gasoline-fueled vehicle due to the insufficient strength examination of the fuel tank's (a gas container's ) installation part. The crack may be enlarged with continued use; in the worst case, the floor panel may be damaged resulting in falling-off of the fuel tank.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBE-NCP51V Kai	「PROBOX」 「SUCCEED」	2012～2014	73
DBE-NCP55V Kai		2012～2014	12
		TOTAL	85