VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3565	DATE	May 14, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	As a result of having investigated inflators collected from the market, airtightness of some driver's airbag inflators were found insufficient. Therefore, atmospheric moisture might enter such an inflator and gas generating propellant absorbs the moisture while a vehicle is used for a long term. Consequently, it is possible that an affected airbag might not deploy normally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-L250S	Mira	2003-2006	123,317
LE-L250V			38,997
UE-L250V			
GBD-L250V			
TA-L260S			18,823
LE-L260V			4,402
DBA-L235S	ESSE	2005-2006	14,156
CBA-L245S			2,158
LE-S320V		2004-2006	37,295
GBD-S320V	HIJET		
HAD-S320V			
LE-S330V			19,107
GBD-S330V			
LE-S320W	HIJET DECKVAN	2005-2006	463
LE-S330W			728
	•	TOTAL	259,446