

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 5 8 7	DATE	J u n . 1 6 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an insufficient heat resistance of the stator coil in the generator, the insulating material will be carburized when the temperature of the said coil becomes high, and a part of the coil may be short-circuited. For that reason, the amount of charging is reduced, and if it is used continuously, the battery will discharge and that will cause the engine to malfunction. In the worst case scenario, the engine may stop and not being able to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B K-S G 2 0 J	Y P 2 5 0	2 0 0 7 ~ 2 0 1 5	2 0, 7 8 1
J B K-D G 1 5 J	W R 2 5 0 R	2 0 0 7 ~ 2 0 1 5	7, 2 3 9
	W R 2 5 0 X		6, 0 0 4
		TOTAL	3 4, 0 2 4