VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3583	DATE	June 11, 2015	
MANUFACTURE	SUMITOMO NACCO MATERIALS HANDLING CO., LTD. (Japan)			
DESCRIPTION OF DEFECT	In accelerator unit of forklift, because a surface treatment for the spring is inappropriate, there is a blemish in some springs. Therefore, the spring is broken if the accelerator operation is frequently done, and there is a possibility that the accelerator pedal does not return in the worst case.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-B1K	FB09PSXII FB10PSXII FB15PSXII FB18PSXII	2014 ~ 2015	44
ZAF-B2K	FB20PSXII FB25PSXII	2014 ~ 2015	13
ZAF-B3E	FD25PXI	2014 ~ 2015	2
	1	TOTAL	59