

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3585	DATE	June 4, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Some of the subject inflators installed in frontal driver air bag could potentially create excessive internal pressure when the air bag is deployment, which could result in the body of the inflator rupturing upon deployment. In the event of the inflator rupture, metal fragments could pass through the airbag cushion metal, which may result in injury to vehicle occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-SE3P ABA-SE3P	Mazda 「RX-8」	2003-2008	32,784
LA-GG3P UA-GG3P	Mazda 「ATENZA」	2002-2005	2,972
LA-GG3S UA-GG3S		2002-2005	12,598
LA-GY3W UA-GY3W		2002-2005	17,733
LA-GGEP UA-GGEP		2002-2005	3,392
LA-GGES UA-GGES		2002-2005	1,574
LA-GYEW UA-GYEW		2002-2005	1,896
		Total	72,949