VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2203	DATE	Jul 3,2015	
MANUFACTURER	TADANO LTD.			
DESCRIPTION OF DEFECT	Due to inadequate instructions regarding the installation of the bolt securing the engine transfer shaft, there are inconsistencies in both the amount of thread locking adhesive applied to bolts and the bolt tightening torque with the possibility of bolts loosening over time with travel related vibration. Therefore, with continued use in this condition, there is a risk of the bolts breaking from repetitive excessive stress of the loose flange movement which, in the worst case, may lead to dislocation of the propeller shaft, and travel failure.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	RTF360G-6	2009 — 2012	30
FAUN	ATF220G-5	2008 — 2015	55
FAUN	ATF160G-5	2006 — 2015	51
FAUN	ATF130G-5	2010 — 2015	42
		TOTAL	178