

VEHICLE SAFETY/POLLUTION RECALLCAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No | GAI-2201 | DATE | July.01.2015 |
| MANUFACTURER | PLOT USA INC. Yoshimitsu Kondo/CEO Plot Group (Japanese Importer. PLOT INC Contact Tel: 0566-36-0557) | | |
| DESCRIPTION OF DEFECT | <p>1) 1)Due to an insufficient wiring harness design at a cam position sensor that detects the ignition signal in the engine ignition device, counter electromotive force cause damage to a cam position sensor and then the motorcycle might be caused being disabled in cold start.</p> <p>2) 2)On the condition that the battery level is low and continuing to push starter switch, the fuse for starter relay might blow out and a cam position sensor might be damaged, and then the motorcycle might be disabled.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | REMARKS |
|------|-----------------|--|-------------------|----------|
| KRD | ROAD HOPPER | 1P9KRD740DL471011~1P9KRD740DL471056 2013/5/8~2013/8/7 | 31 | 1) 2) |
| | | 1P9KRD742DL471057~1P9KRD746DL471112 2013/8/7~2014/7/2 | 30 | 1) |
| | | TOTAL | 61 | |