VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2211	DATE	August 3, 2015	
MANUFACTURER	Hyundai Motor Company (Japanese importer :Hyundai Motor Japan Co., Ltd)			
DESCRIPTION OF DEFECT	The warning switch for emergency exit is mounted in cover of emergency exit lever of the inside of car. Therefore when emergency exit is opened from the inside, warning device operates. But, if emergency exit is opened from the outside, warning device does not operate. As the result, it cannot warn driver of opening of emergency exit.			

	0014455044	110051.7510	\!!!! 4DED 0E
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ADG-RD00	UNIVERSE	2008~2010	119
LDG-RD00		2010~2015	256
		TOTAL	375