VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2275	DATE	Nov. 30, 2015	
MANUFACTURER	DUCATI MOTOR HOLDING SpA			
	(Japanese Importer : DUCATI JAPAN Ltd.)			
DESCRIPTION OF DEFECT	By the wrong welding joint of side stand articular part, it is			
	occurred side stand broken due to vehicle load at parking.			
	In worst case, vehicle going to rollover at parking or side stand			
	pipe structure falling off and becomes traffic obstacle			
	Authorized Ducati dealers will check side stand batch number			
	and they replace side stand in case of wrong batch number matched or they undetermined correct batch number by batch			
	number sticker disappeared.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-AA02	MULTISTRADA 1200	2015	7
	MULTISTRADA 1200 S	2015 - 2016	98
		TOTAL	105