VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3677	DATE	Nov.18.2015	
MANUFACTURER	ΤΟΥΟΤΑ			
DESCRIPTION OF DEFECT	Due to inaccurate dimensions of ring-shaped piston and seal in hydraulic clutch system in continuously variable transmission, the piston and seal are possibly installed in a misaligned position. It leads to damage of the seal and malfunction of clutch, in the worst case, becoming unable to travel.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE141	[COROLLA Axio]	2006-2008	58,122
DBA-NZE144		2006-2008	7,531
DBA-ZRE142		2006-2008	10,081
DBA-ZRE144		2006-2008	1,215
DBA-NZE141G	[COROLLA FIELDER]	2006-2008	66,328
DBA-NZE144G		2006-2008	10,496
DBA-ZRE142G		2006-2008	19,564
DBA-ZRE144G		2006-2008	5,021

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE151N	[COROLLA RUMION]	2007-2008	21,894
DBA-ZRE152N		2007-2008	11,193
DBA-ZRE154N		2007-2008	3,728
DBA-NZE151H	[AURIS]	2006-2008	30,203
DBA-NZE154H		2006-2008	4,216
DBA-ZRE152H		2006-2008	15,009
DBA-ZRE154H		2006-2008	2,536
DBA-NZT260	[PREMIO] [Allion]	2007-2008	21,600
DBA-ZRT260		2007-2008	34,589
DBA-ZRT265		2007-2008	6,160
DBA-NCP110	[ist]	2007-2008	14,052
DBA-NCP115		2007-2008	2,661
L	1	TOTAL	346,199