## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2176	DATE	Nov. 10, 2015
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	By the wrong structure of throttle cable housing, it is occurred		
	throttle cable too bended. The throttle cable will folded orthrottle		
	operation will frictioned. In worest case, it cannot throttle		
	operation and running due to throttle cable break.		
	Authorized Ducati dealers will replace the upper throttle cover		
	with a newly designed equivalent that inhibits the possibility of		
	inner throttle sleeve d	lisengagement.	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
TYPE	NAME	RECALLED	VEHICLE
ZDMA200ABAB	MULTISTRADA1200 ABS	2010 - 2011	54
ZDMA200ABBB	MULTISTRADA1200 ABS	2011 - 2012	10
ZDMA200ABCB	MULTISTRADA1200 ABS	2012	10
ZDMA200ACAB	MULTISTRADA1200S Touring	2010 - 2011	192
ZDMA200ACBB	MULTISTRADA1200S Touring	2011 - 2012	95
ZDMA200ACCB	MULTISTRADA1200S Touring	2012	25
ZDMA200ADAB	MULTISTRADA1200S SPORT	2010 - 2011	166
ZDMA200ADBB	MULTISTRADA1200S SPORT	2011 - 2012	38
ZDMA200ADCB	MULTISTRADA1200S SPORT	2012	18
ZDMA200AEBB	MULTISTRADA1200S PIKES PEAK	2011 - 2012	20
ZDMA200AECB	MULTISTRADA1200S PIKES PEAK	2012	28
	MULTISTRADA1200 ABS		
ZDMA302JACB	MULTISTRADA1200S PIKES PEAK	2013	112
	MULTISTRADA1200S Touring		

ZDMA302JADB	MULTISTRADA1200 ABS		256
	MULTISTRADA1200S PIKES PEAK	9019 9014	
	MULTISTRADA1200S Touring	2013 - 2014	
	MULTISTRADA1200S Granturismo		
ZDMA302JAEB	MULTISTRADA1200S PIKES PEAK		
	MULTISTRADA1200S Touring 2014		70
	MULTISTRADA1200S Granturismo		
		TOTAL	1094