

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3711	DATE	December 11.2015
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	At fuel device on reaping and threshing vehicle, safety regulation is not satisfied; clearance between orifice of the breather pipe and exposed terminals doesn't reach 200mm, as the pipe on fuel tank was inappropriately routed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-C114	「AG6100」	2012-2013	17
	「AG6114」	2011-2013	33
	「AG7114」	2014-2015	11
-	「AG6100R」	2014-2015	67
	「AG6114R」	2014-2015	40
	「AG7114R」	2014	1
TOTAL			169