

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2279	DATE	Dec 10, 2015
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in 2009-2012 MY Chevrolet Traverse vehicle built prior to March 1, 2012 and equipped with a power lift gate (TB5 or E61). These vehicles may have a condition in which the gas struts that hold the lift gate up may prematurely wear. These vehicles have a Prop Rod Recovery system intended to accomplish a controlled, slow return of the lift gate to the closed position if the lift gate's gas struts are no longer capable of supporting the weight of the lift gate. However, in some cases, the lift gate's Prop Rod Recovery system software may be unable to detect/stop a lift gate with prematurely worn gas struts from falling too quickly after the lift gate is opened. If the open lift gate unexpectedly falls, it may strike a person, increasing the risk of injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「Unknown」	「Traverse」	2009 - 2011	87
		TOTAL	87