

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3965	DATE	Jan. 19, 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	In the front strut of the subject vehicles, tightening nuts may loosen with shock input (driving over a curb, etc.) due to insufficient looseness evaluation for strut upper mount fasteners. After extended operation with such condition, the faster portion may have play and damage, a noise may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-BL5 ABA-BL5 CBA-BL5	「LEGACY」	2003~2009	29,990
DBA-BL9		2008~2009	202
UA-BLE CBA-BLE DBA-BLE		2003~2009	8,736
TA-BP5 ABA-BP5 CBA-BP5		2003~2009	67,384
DBA-BP9		2008~2009	201
UA-BPE CBA-BPE DBA-BPE		2003~2009	9,883
		TOTAL	116,396