## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

RECALL No.	Gai-2341	DATE	Feb. 3, 2017	
MANUFACTURER	Ford Motor Company			
	(Japanese Representative: PCI Ltd.)			
DESCRIPTION OF	SAFETY RECALL: Certain 2008 Model Year Lincoln MKXFuel Tank Check and			
	Replacement.			
DEFECT	In some of the affected vehicles operating in high-corrosion environments associated with road salt use, moisture and salt may become trapped under the fuel tank mounting reinforcement brackets at the four corners where the fuel tank is attached to the vehicle. Over time, corrosion under these reinforcement brackets can spread to the fuel tank which can result in a fuel leak. A fuel leak in the presence of an ignition source may result in a fire.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Lincoln MKX	2018	98 units
L		TOTAL	98 units