

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2437	DATE	Feb 16, 2017
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	Certain 2009-2013 model year Chevrolet Corvette vehicles that are equipped with an electronic column lock (ECL) (NP7) and located in Japan, may have a condition where the column lock may not unlock when starting the vehicle. This condition could prevent the customer from driving the vehicle because vehicle power would be inhibited by the Powertrain Control Module (PCM), which will shut off the fuel when the vehicle starts to move. The first time the failure is detected, a "Pull Key, Wait 10 Sec" Driver Information Center (DIC) message will be displayed. If the condition continues to be present, a "Service Column Lock" DIC message will be displayed with subsequent key cycles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「ABA-X245S」	「Corvette」	2009 - 2011	90
「ABA-X245S」	「Corvette Z16」	2011-2012	48
「-X245S-」	「Corvette Z16」	2013	30
「ABA-X245A」	「Corvette Z06」	2009-2012	28
「-X245A-」	「Corvette ZR1」	2010 - 2012	31
		TOTAL	227