## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai –2439	DATE	February 6, 2017
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG		
	(Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the fastening screws for the fuel		
	collection pipes on the affected vehicles can shear off due to		
	stress corrosion cracking.		
	If this happens, the high fuel pressure that builds up in the		
	fuel injection system when the engine is running can press		
	the relevant fuel collection pipe off the fuel injectors. This		
	can cause a fuel leak in the engine compartment.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-982H1	718 Boxster	2017	63
	718 Cayman		1
ABA-982H2	718 Boxster S		46
	718 Cayman S		1
ABA-991H1	911 Carrera		214
	911 Carrera 4		52
	911 Carrera S		207
	911 Carrera 4S		90
	911 Targa 4		3
	911 Targa 4S		7
		TOTAL	684