

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3976	DATE	Feb. 2, 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>In the vacuum pump of brake booster device, due to an inappropriate manufacturing process of the pump, foreign material may remain inside the pump. If this material blocks the flow of lubrication oil, damage may occur inside the pump because of poor lubrication. If this were to occur, vacuum brake assist functionality may be lost, lowering of brake performance may occur when braking with regular pedal force at high altitude etc.</p> <p>Also, debris of damaged parts inside the pump may enter into the engine and the engine may be damaged.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK6	「IMPREZA」	2016~2016	24
DBA-GK7		2016~2016	70
DBA-GT6		2016~2016	63
DBA-GT7		2016~2016	156
		TOTAL	313