

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3987	DATE	February 20 ,2017
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		Due to inappropriate clearance between a bellows of buffer device 'air suspension' and a mounting bolt of rear leaf spring, the face of the bellows may be worn caused through interferes between itself with the mounting bolt when operations of lowered body are repeated. This will result in a risk that the bellows is damaged and thereby the vehicle is unable to drive in the worst case.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-NPR81AN "kai" (modified)	"ELF"	2005-2006	2
VD-NPR81AN "kai" (modified)		2007	1
BDG-NPR85AN "kai" (modified)		2007-2009	3
BDG-NPR85N "kai" (modified)		2008	1
BDG-NPS85AN "kai" (modified)		2008-2010	6
BKG-NPR85AN "kai" (modified)		2011	2
SDG-NPS85AN "kai" (modified)		2012	1
SKG-NPR85AN "kai" (modified)		2011-2012	3
SKG-NPR85YN "kai" (modified)		2013	1
TDG-NPS85AN "kai" (modified)		2012-2013	5
TKG-NPR85AN "kai" (modified)		2012-2014	19
TKG-NPR85YN "kai" (modified)		2016	3
TKG-NPS85AN "kai" (modified)		2015-2016	4
TPG-NPR85AN "kai" (modified)		2015-2016	8
TPG-NPR85AR "kai" (modified)		2016	1
TRG-NPR85AN "kai" (modified)		2015-2016	17
		TOTAL	77