

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3990	DATE	Feb.2017
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>The road roller has the following issues.                  Because flexibility of the wiring in the wire harness which did routing in the body refraction department-resistant is insufficient, therefore the crack occurs in wiring when excessive power appears at the time of the refraction of the body.                  If this continue using, the crack of the wiring progresses and disconnection and cannot change the speed, and cannot release the parking brake.                  In the worst case, the following failures can happen: might not be able to run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「ZC35C-3」	2013~2015	485
—	「HW30VWH-5」	2013~2015	41
—	「ZC35T-3」	2013~2015	20
—	「HW30VSH-5」	2014	5
—	「ZC50C-3」	2013~2015	639
—	「HW41VWH-5」	2013~2015	47
—	「ZC50T-3」	2013~2015	27
—	「HW41VSH-5」	2014~2015	2
		TOTAL	1266