

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3993	DATE	February 16, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the camera which confirms the situation in front of and on the left side of the vehicle, due to inappropriate coating of the lens surface, the acid included in the cleaning agent, rain, and so on, may corrode the coating, and continuous use may make the lens itself corroded and clouded, the view of the side camera may not be clear gradually. In the worst case, the driver may not confirm the situation in front of and the left side of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KE2AW	Mazda 「CX - 5」	2012-2014	24,336
LDA-KE2FW		2012-2014	27,297
DBA-KE5AW		2012-2014	726
DBA-KE5FW		2012-2014	439
DBA-KEEAW		2012-2013	2,958
DBA-KEEFW		2012-2014	11,657
		Total	