

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2451	DATE	March 3 rd , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to a fault in the manufacturing process of the circuit board inside the control unit of electric power steering, the pins might not have been welded properly. When the pin welding comes off, this might lead to a loss of power steering assistance. In worst case, a thermal incident might occur due to a gradually increasing contact resistance on the circuit board.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-WY20	BMW X3 xDrive 20d	2015	6
LDA-KS30	BMW X5 xDrive 35d	2015	1
		TOTAL	7