VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4038	DATE	April 21.2017		
MANUFACTURER	YANMAR CO.,LTD.				
DESCRIPTION OF DEFECT	partially improper cor transmission for turn generate corrosion, t cause the situation the transmission for turn	The agricultural tractors have an emergency operating lever with partially improper configuration in its hydrostatic continuously variable transmission for turn. The lever may collect water at the bottom and generate corrosion, then might get stuck with the corrosion. It might cause the situation that the hydrostatic continuously variable transmission for turn would not be operated, leading total loss of steering or engine stall in the worst case.			

TYPE COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLE	
_	「YT5113C」	2015-2016	97	
	TOTAL	97		