VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4029		DATE	April 14, 2017
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	For the transmission of the harvester combines, because the design of the vice-shifting arm is inappropriate, the vice-shifting arm may be damaged when operate it in the state that it is hard to change gears into. Therefore, the use in the condition may lead to progresses a damage, and in the worst case scenario, the harvester combines leads to running impossibility.			
TYPE	COMMERCIAL NAME	-	IODEL YEAR CALLED	NUMBER OF VEHICLE
WDP-H161	「НЈ5098G」	2014-2015		140
	ГНЈ6098GЈ	2014-2015		132
XDN-H162	「HJ4075G」	2014-2015		72
XDN-H163	「HFR575G」	2014-2015		142
YDN-H164	「HFR463G」	2015		95
YDN-H165	「HFR450G」	2015		71
			TOTAL	652