## 

CAMPAIGN No.	4024	DATE	14. 04. 2017	
MANUFACTURER	HANTA MACHINERY CO. LTD.			
DESCRIPTION OF DEFECT	Due to insufficient evaluation against water-proofing when developing asphalt pavers, rainwater, etc. may be penetrated to inside of machine from top of rear-cover, and then water may get splashed on the terminal connector for wiring of engine controller power relay. Accordingly, if using the machine under this condition, the terminal connector will be corroded and the engine controller power relay will malfunction, and then, in the worst case, there is a potential danger that engine will stop and will never start again.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM—F25W5	1432W	2015~2016	92
	25W		
		TOTAL	92

(日本工業規格A列4番)