VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4016	DATE	April 6,2017		
MANUFACTURER	MITSUBISHI MOTORS CORPORATION				
	The lock mechanism in the door latch may not operate properly when				
DESCRIPTION OF DEFECT	the temperature become high due to insufficient precision of the part				
	caused by inappropriate manufacturing process of the component				
	parts. As a result, the door may not be locked securely and, in the worst				
	case, the door may open while driving.				

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DLA-GG2W	$\lceil ext{OUTLANDER} brace ext{PHEV} floor$	$2015\sim\!2016$	10,560
DBA-GF7W	「OUTLANDER」	$2015\sim\!2016$	1,261
DBA-GF8W	OUILANDER]	$2015\sim2016$	2,397
DBA-GA4W	$\lceil \mathrm{RVR} \rfloor$	$2015\sim\!2016$	1,574
DBA-B11W	$\lceil_{\mathbf{eK}} floor$	2015	7,370
DBA-B11A	「eK SPACE」	$2015{\sim}2016$	7,932
DBA-B21W	$\lceil \mathrm{DAYZ} floor$	2015	18,650
DBA-B21A	「DAYZ ROOX」	2015~2016	24,167
		TOTAL	73,911

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
FRONT DOOR LATCH (RIGHT)	5715B048	2015	57
REAR DOOR LATCH (LEFT)	5745A345	2015	9
REAR DOOR LATCH	5745A346	2015	20
(RIGHT)	5745A396	$2015\sim2016$	268