## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## **Domestic Vehicles**

CAMPAIGN No.	4014	DATE	May 18, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF	On passenger seats for driving training car, due to insufficient		
	strength of the seat height adjustment lifter link, or, due to		
DEFECT	inadequate attachment method of the lifter link push nuts, the lifter		
	link may become cracked or the push nuts may become separated.		
	Therefore, in continuous use, abnormal noise and/or rattle are		
	occurred from the seat. In the worst case, the seat lifter link may be		
	broken or detach, t	he seat angle ma	y incline, leading to
	inappropriate position.		

TYPE	COMMERCIAL NAME	MODEL	
		YEAR	NUMBER OF VEHICLE
		RECALLED	
ABA-BL6FJ	Mazda「Axela」	2009-2010	659
		Total	659