

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4046	DATE	May 19, 2017
MANUFACTURER	Unicarriers		
DESCRIPTION OF DEFECT	In diesel engine of forklift, since the structure of the bracket fixing the exhaust pipe is improper, cracks might occur on the exhaust pipe due to engine vibration. As such, if it is used continuously in the same condition, cracks might proceed, in the worst case exhaust pipe may be broken and exhaust gas may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
WDR-F172	FD120-5	2015 2016 2017	13
		TOTAL	13