VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4047	DATE	May 25,2017
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Improperly coated at the end cap section, the outer pipe of the gas- filled back door stay may corrode by influence of salt air in coastal districts. If a vehicle with this condition is used continuously, it may happen that corrosion progresses, the outer pipe swells, the end cap breaks, and then the outer pipe fractures when the back door is opened. In the worst case, people being around the back door may be injured consequently.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA250S	CAST	2015-2016	50,949
DBA-LA260S			10,898
		TOTAL	61,847