

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4067	DATE	June 15,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	The oil passage in the cylinder block of the engine may not completely pass through due to abnormal casting process of the cylinder block in which the core of the mold had been placed improperly. As a result, the journal metal of the crank shaft may burn out causing abnormal noise due to lack of oil supply. In the worst case, the engine may burn out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B11W	「eK」	2017	44
DBA-B21W	「DAYZ」	2017	213
		TOTAL	257