

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2492	DATE	06.23.2017
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>① FIELD SERVICE ACTION: Certain 2014-15 Model Year EcoSport. -ABS (Anti-Lock Brake) Module Reprogram. On certain vehicles, the steering column lock may not function under certain conditions due to a communication error between the ESC (Electronic Stability Control) module and the KVM (Keyless Vehicle Module). This does not comply with General Requirements of ECE Regulation 116, Anti-Theft Devices and Immobilizers.</p> <p>② FIELD SERVICE ACTION: Certain 2014-15 Model Year EcoSport. -BCM (Body Control) Module Reprogram. Vehicles have been built with a Drive Away Locking personalization feature enabled, which does not comply with ECE 94 regulation.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR FIELD SERVICE ACTION	NUMBER OF VEHICLE
ABA-MAJUEJ	EcoSport	2014-2015	1191 units
TOTAL			1191 units