

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2498	DATE	June 26 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to improper manufacturing of the joint disk, which connects the propeller shaft and transmission on power transmission mechanism, the joint disk might not be robust enough. Thus, the disk might be damaged by drive torque. When keep driving under this condition, noise may occur while driving, then the propeller shaft might come off, and in worst case, it is not possible to drive further.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UC30	BMW 135i Coupe	2011	54
ABA-PM35	BMW 335i	2011	41
ABA-UV35	BMW 335i Touring	2011	9
ABA-KG35	BMW 335i Coupe	2011	36
ABA-DX35	BMW 335i Cabriolet	2011	59
DBA-FR35	BMW 535i	2011	72
DBA-MU35	BMW 535i Touring	2011	15
DBA-SN30	BMW 535i Gran Turismo	2011	2
ABA-SP44	BMW 550i xDrive Gran Turismo	2011	1
DBA-LW30	BMW 640i Cabriolet	2010 - 2011	76
ABA-KA30	BMW 740i	2011	44
ABA-LM30	BMW Z4 sDrive 35i	2011	28
		TOTAL	437