VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

Gai-2503	DATE	July 3, 2017	
Automobiles Voly			
Automobiles Volvo Car Corporation			
(Japanese Importer: Volvo Car Japan Limited)			
Water leakage between first lid and sealing, due to insufficient			
sealing function in first lid of the fuel filler pipe insert.			
If too much water is	If too much water is present in the fuel, the customer may		
experience low engin	experience low engine performance.		
	In a worst-case scenario the vehicle may be difficult to start		
	The corrective action is to replace the Fuel Filler Insert.		
	MODEL	NUMBER OF	
NAME		VEHICLE	
	REGALLED		
[V40]	2016	1594	
[V40CC]	2016	563	
	TOTAL	2157	
- -	Water leakage between sealing function in If too much water is experience low engine In a worst-case scena and in some cases sta The corrective action COMMERCIAL NAME [V40]	Water leakage between first lid and sealing sealing function in first lid of the fuel If too much water is present in the fuel, experience low engine performance. In a worst-case scenario the vehicle may b and in some cases stalling. The corrective action is to replace the Fu COMMERCIAL MODEL NAME YEAR RECALLED [V40] 2016 2016	