

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4078	DATE	July 27, 2017
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the select lever of automatic gearbox, due to inappropriate setting of the welding machine, the welding between select lever and bracket may be insufficient. Therefore, the welding point may be broken by operation of the select lever, drivers may be not able to operate the lever.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2V	Mazda「Bongo」	2015	433
ABF-SKP2M		2015	65
ABF-SKP2T		2015	215
ABF-SKP2L		2015	12
DBF-SLP2V		2016	1,283
DBF-SLP2M		2016	509
DBF-SLP2T		2016	725
DBF-SLP2L		2016	136
ABF-SKP2MN	NISSAN「VANETTE」	2015	375
ABF-SKP2TN		2015	442
ABF-SKP2LN		2015	94
		Total	4,289