

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 0 8 6	DATE	July.27.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the vehicles which replaced the front passenger airbag inflator, because the exhaust hole of the airbag is small, crack occurs to the airbag mounting bracket and airbag exhaust hole may be torn when the airbag is deployed. Therefore, the airbag might not be deployed appropriately, in an extreme case, the occupant protection performance might be decreased.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
TA-FG10	BLUEBIRD SYLPHY	2001	7
UA-QG10		~	18
TA-QNG10		2001	5
GH-TG10			1
		TOTAL	31