

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4 0 9 4	DATE	August 30, 2017
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>In the electric device of the load roller, since the wiring of the battery relay power cable is improper, due to the vibration of the vehicle, the cable may contact the minus earth cord of the engine and wear. Therefore, if you continue to use it as it is, the cover of the power cable for battery relay and the cover of the engine minus earth cord will peel off and short circuit occurs, and in the worst case it may be difficult to stop or restart the engine.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VMW 2	「MW700」	2006 - 2010	19
		TOTAL	19