

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

|                       |   |      |                       |
|-----------------------|---|------|-----------------------|
| CAMPAIGN No.          | 4 1 1 1   | DATE | S e p . 2 0 . 2 0 1 7 |
| MANUFACTURER          | YAMAHA MOTOR CO., LTD.  |      |                       |
| DESCRIPTION OF DEFECT | <p>As for the main harness, due to wiring variations, water from washing the vehicle, etc. may be collected inside the coupler cover which is connected to the rectifier, and the electric wires may corrode.</p> <p>Because of that, when it is used continuously, the electric wires may further corrode and that may cause the electric wires to be disconnected, and furthermore, it will become impossible to recharge the electric power.</p> <p>As a result, the lighting parts such as a horn or a turn signal lamp, etc. may not activate correctly.</p> <p>In the worst case scenario, the engine may stop while running, and it may become impossible to start the engine again.</p> |      |                       |

| TYPE              | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------------|-----------------|---------------------|-------------------|
| J B H - S A 5 2 J | V O X X F 5 0 D | 2 0 1 5 ~ 2 0 1 7   | 3 , 5 7 1         |
|                   |                 | TOTAL               | 3 , 5 7 1         |