## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/<del>Import</del> Vehicles

CAMPAIGN No.	412	2	DATE	October 3, 2017
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	Because the strength of wheel disk in the front wheel of agricultural tractor is insufficient, crack in wheel disk may occur when operating with attaching the front loader as implement. Therefore, wheel disk might be damaged if it keeps using it under such a condition and in the worst case, the front wheel may come out.			
ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
T123F	「TH20」	2001-2007		4, 189
T126F	「TH24」	2001-2006		87
T157F	「TH213」	2007-2010		2,146
EDM-T157F	「TH253」	2007-2010		29
T183F	「TH235」	2010-2014		38
EDM-T184F	「TH265」	2010-2014		46
			TOTAL	6, 535