

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4124	DATE	Oct. 5. 2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty buses, due to the improper program of the engine control computer, the discharge of carbon monoxide exceeds the standard of Safety Regulations for Road Vehicles in acceleration. Also, the discharge of dry soot may increase, therefore, DPR (diesel particulate active reduction system) may be blocked up by PM (particulate matter) and the engine warning lamp may be illuminated, resulting the DPR to be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-RU1ASDA	[HINO SELEGA]	2017	28
		TOTAL	28