VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4125	DATE	October 5 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty buses, due to the improper program of the engine control computer, the discharge of carbon monoxide exceeds the standard of Safety Regulations for Road Vehicles in acceleration. Also, the discharge of dry soot may increase, therefore, DPR (diesel particulate active reduction system) may be blocked up by PM (particulate matter) and the engine warning lamp may be illuminated, resulting the DPR to be damaged.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2TG-RU1ASDJ	[ISUZU GALA]	2017	23
		TOTAL	23