

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4127	DATE	19 October, 2017
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the braking devices, due to improper routing of the brake air nylon tube, when driving on rugged roads, the propeller shaft may contact the brake air nylon tube. If the vehicle is operated under these conditions, the brake warning lamp may be activated due to air leakage from the damaged nylon tube. In the worst case scenario, the braking performance may be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CW5XL	Quon	2014-2017	2,825