

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4130	DATE	October.26, 2017
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For certain door mirrors, the movable contact in the mirror switch has been applied with inadequate surface treatment whereby the movable contact may wear and generate wear debris through repetition of the switch operation. If the vehicle continues in service in such a condition, wear debris would accumulate and would be oxidized, increasing the contact resistance. Should this happen, the door mirror could retract unexpectedly while driving or during a stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RC1	「ODYSSEY」	2013～2017	67,932
DBA-RC2			7,565
DAA-RC4		2016～2017	30,175
DAA-RU3	「VEZEL」	2013～2016	70,236
DAA-CR6	「ACCORD HYBRID」		21,717
DAA-FR4	「JADE」	2015～2017	15,477
DBA-FR5			4,468
DAA-CR7	「ACCORD」	2016～2017	4,452
DLA-CR5	「ACCORD PLUG IN HYBRID」	2013～2015	239
		TOTAL	222,261