

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4132	DATE	Oct. 31. 2017
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium-duty trucks, due to the insufficient strength of the rear bumper stays on the bumper, a crack may be formed in the rear bumper stays when the bumper interferes with bumps in the road. Therefore, if it is used under the condition continuously, the rear bumper stays may break and in the worst case, the bumper may drop on the road resulting it to disturb the safety of traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-FC7JDAA	[HINO Ranger]	2015~2016	18
SDG-FC7JEAA		2015~2016	78
TKG-FC7JGAA		2015~2016	46
TKG-FC7JHAA		2015~2016	57
TKG-FC7JHAG			
TPG-FC7JHAA			
TPG-FC7JHAG			
TKG-FC7JJAA		2015~2016	144
TKG-FC7JJAG			
TPG-FC7JJAA			
TKG-FC7JKAA		2015~2016	297
TKG-FC7JKAG			
TPG-FC7JKAA			
TPG-FC7JKAG			
TKG-FC7JLAA		2015~2016	51
TKG-FC7JLAG			
TPG-FC7JLAG			
TKG-FC7JNAA	2015~2016	23	
TKG-FC7JNAG			
TPG-FC7JNAA			
SDG-FC9JCAA	2015~2016	391	
SDG-FC9JCAP			
TKG-FC9JCAA			
TKG-FC9JCAP			
SDG-FC9JDAA	2015~2016	162	
TKG-FC9JDAA			
TKG-FC9JDAP			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-FC9JEAA TKG-FC9JEAA TKG-FC9JEAP	[HINO Ranger]	2015~2016	645
SDG-FC9JGAP TKG-FC9JGAA TKG-FC9JGAG TKG-FC9JGAP		2015~2016	193
TKG-FC9JHAA TKG-FC9JHAG TKG-FC9JHAP		2015~2016	226
TKG-FC9JJAA TKG-FC9JJAG TKG-FC9JJAP		2015~2016	1,048
SDG-FC9JKAP TKG-FC9JCAA TKG-FC9JKAG TKG-FC9JKAP TQG-FC9JKAQ		2015~2016	3,155
TKG-FC9JLAA TKG-FC9JLAG TKG-FC9JLAP		2015~2016	519
TKG-FC9JNAA TKG-FC9JNAG		2015~2016	141
TKG-FC9JSAA TKG-FC9JSAG		2015~2016	20
SDG-FD7JDAA		2015~2016	34
SDG-FD7JEAA		2015~2016	122
SDG-FD7JGAA TKG-FD7JGAA TKG-FD7JGAG TPG-FD7JGAA TPG-FD7JGAG		2015~2016	181
TKG-FD7JJAA TKG-FD7JJAG TKG-FD7JJAJ TPG-FD7JJAA TPG-FD7JJAG		2015~2016	192

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FD7JKAA TKG-FD7JKAG TKG-FD7JKAJ TPG-FD7JKAA TPG-FD7JKAG	[HINO Ranger]	2015~2016	404
TKG-FD7JLAA TKG-FD7JLAG TKG-FD7JLAJ TPG-FD7JLAA TPG-FD7JLAG TPG-FD7JLAJ		2015~2016	3,930
TKG-FD7JMAA TKG-FD7JMAG TKG-FD7JMAJ TPG-FD7JMAA TPG-FD7JMAG		2015~2016	344
TKG-FD7JPAA TKG-FD7JPAG TKG-FD7JPAJ TPG-FD7JPAA TPG-FD7JPAG TPG-FD7JPAJ		2015~2016	555
TKG-FD7JUAA TKG-FD7JUAG TPG-FD7JUAA TPG-FD7JUAG		2015~2016	260
TKG-FD7JWAA TPG-FD7JWAA		2015~2016	18
TKG-FD9JDAA		2015~2016	33
TKG-FD9JEAA		2015~2016	47
TKG-FD9JGAA		2015~2016	120
TKG-FD9JJAA TKG-FD9JJAG		2015~2016	137
TKG-FD9JKAA TKG-FD9JKAG		2015~2016	271
TKG-FD9JLAA TKG-FD9JLAG		2015~2016	2,713
TKG-FD9JMAA TKG-FD9JMAG		2015~2016	138
TKG-FD9JPAA		2015~2016	130

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FD9JUAA	[HINO Ranger]	2015	2
SDG-FX7JEAA		2015~2016	62
SDG-FX7JGAA		2015~2016	38
SDG-FX7JJAA		2015~2016	19
SDG-FX7JCAA		2015~2016	11
SDG-FX7JLAA		2015~2016	21
		TOTAL	16,996

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-FD7JGAA	[HINO Ranger]	2016	1
TKG-FD7JLAG		2014	1
		TOTAL	2

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
REAR BUMPER STAY	52087-E0310	2013~2017	204
	52087-E0320		
	52088-E0310		
	52088-E0320		
		TOTAL	204