

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	4141	<b>DATE</b>	Nov 24 , 2017
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	<p>Due to improper manufacturing process of front suspension frame, lower arm mount bracket of suspension frame may corrode by corrosion-promoting substances such as saltwater.</p> <p>Therefore, if the vehicle is driven continuously in this condition, lower arm mount bracket may break due to corrosion promotion, in the worst case, it becomes impossible to drive the vehicle by falling lower arm off the vehicle.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
CBA-MH21S	WAGON R	2007	3,235
CBA-MH22S			23,732
DBA-MH21S			23,573
DBA-MH22S			43,293
GBD-HA24V	ALTO		5,850
CBA-HA24S			1,858
DBA-HA24S			14,708
CBA-MF22S	MR WAGON		3,932
DBA-MF22S			21,977

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
CBA-HG21S	<b>CERVO</b>	<b>2007</b>	<b>6,969</b>
DBA-HG21S			<b>7,587</b>
CBA-HC24S	<b>PINO</b>		<b>939</b>
DBA-HC24S			<b>12,697</b>
CBA-MG22S	<b>MOCO</b>		<b>2,604</b>
DBA-MG22S			<b>22,940</b>
CBA-MJ21S	<b>AZ-WAGON</b>		<b>302</b>
CBA-MJ22S			<b>1,254</b>
DBA-MJ21S			<b>4,504</b>
DBA-MJ22S			<b>5,932</b>
CBA-HB24S			<b>CAROL</b>
DBA-HB24S	<b>2,753</b>		
		<b>TOTAL</b>	<b>210,876</b>