## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

			Domestic Import Vehicles		
CAMPAIGN No.	Gai-2565	DATE	November 27, 2017		
MANUFACTURE	Tesla, Inc				
	(Japanese Importer: Tesla Motors Japan GK)				
DESCRIPTION OF	On second row 2-seater seats with installed seatbelts, cables that control the reclining mechanism may have been misadjusted due to the inappropriate				
DEFECT	manufacture. Therefore, the reclining position. In such seatbelts during a crash, where the seatbelts during a crash where the seatbelts during the seatbelts during a crash where the seatbelts during t	ne seatback may become a case, such seatback may m	insufficiently fixed in the ove forward with installed		

Vehicle name	Туре	Commercial name	Model Year Recalled	Number of vehicles	Note
Tesla	NA	Model X	5YJXDCE2XHF024284 ~ 5YJXDCE25HF063901 12/27/2016 ~ 9/15/2017	42	Standard
	NA	Model X	5YJXDCE45GF024287 ~ 5YJXDCE44HF064393 12/27/2016 ~ 9/15/2017	14	Performance
	Total (1Type)	Total (1Model)	(all the vehicles imported during imported period) 12/27/2016 ~ 9/15/2017	Total (56)	

scenario.