

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 1 6 0	DATE	Dec. 14. 2017
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD		
DESCRIPTION OF DEFECT	<p>1) Some of medium duty dump trucks have spare tyre carriers whose bolts to hold winch are improperly mounted, not tightened enough, and lose axial tension. Driving the vehicles without repairing it, the bolts can be loosened due to vibration while driving, winches and spare tyre carriers (hereinafter referred as "winches, etc.") can be tilted. In the worst case, winches, etc. can drop off and disturb other traffic.</p> <p>2) Some of medium duty dump trucks have wrong bolts and nuts for brackets to fix chassis frames and sub frames due to improper manufacturing.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-FC2ABA	HINO RANGER	2017	97	1) :97 2) :88
2KG-FD2ABA		2017	1	1) :0 2) :1
TOTAL			98	1) :97 2) :89